



Important Addendum for
Mark II Quiet Knight™
Instruction Manual

Please refer to Item 8, Fault Finding, on Page 9.

The emergency battery backup supply problem and remedy section is now no longer applicable.

This should be replaced by the following:

PROBLEM	POSSIBLE CAUSE	REMEDY
Unit will not lower, handset and power are OK	Anti-crush device has operated	Raise the unit to its fully extended height and lower

If you require any further details, please do not hesitate to contact your local Sales Representative, or the office direct:

Aidapt Bathrooms Limited
1-5 South Norwood Hill
London, SE25 6AA

Telephone: +44 (0) 208 771 2147
Facsimile: +44 (0) 208 771 9969
E-mail: sales@aidaptltd.co.uk